




Parts needed to mount the 45-MDF extrusion



Extrusion (A)



LED strip (B)



Cover (C)



End Cap (D)


Tools needed for mounting:

- mounting glue


NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure.
More mounting procedures and related accessories can be found at www.klusdesign.eu

1. Mount the LED strip (B) in the extrusion (A), insert the cover (C) and the end caps (D).



2. Feed the power cable. Spread the glue on the mounting surface.



3. Connect power to the LED strip and attach the extrusion (A) to the mounting surface.

