





Parts needed to mount the DP-45-MOC-ZZ fastener




Tools needed for mounting:


- Allen wrench
- drill
- soldering tool

NOTE! A list of products corresponding with the selected accessories is available at klusdesign.com

- 1.** Insert an assembled lighting fixture into the mounting bracket of the head (A) and connect the power cable to the power connector (C).



- 2.** Insert the rod into the mounting bracket of the head (D). Block the rod by tightening the pressure screw in the head with the Allan wrench.



- 3.** Suspend the lighting fixture using a selected suspension and power supply system.

