




**Parts needed to mount the DP-MOC-ZZ fastener****Tools needed for mounting:**


- drill
- pliers
- Allen wrench
- soldering tool

NOTE! A list of products corresponding with the selected accessories is available at klusdesign.com.

- 1.** Insert an assembled lighting fixture into the mounting bracket of the head (A) and connect one pole of the cable to the power connector (C).



- 2.** Insert the rod into the mounting bracket of the head (D). Block the rod by tightening the pressure screw in the head with the Allen wrench.



- 3.** Suspend the lighting fixture using a selected suspension and power supply system

