




Parts needed to mount the PAC-MDF extrusion



Extrusion (A)



End caps (B)



Cover (C)



LED strip (D)


Tools needed for mounting:

- mounting glue

WARNING! All LED strips should be connected to a 12 V or 24 V power supply.

IMPORTANT: The mounting instructions present the basic form of assembly.
More methods and related accessories can be found at www.KlusDesign.eu

- 1.** Mount the LED strip (D), insert the cover (C), and then insert the end cap (B). Feed the power cable.



- 2.** Apply glue to the mounting surface. Connect power and mount the extrusion.

