




### Parts needed to mount the PDS-MDF extrusion



Extrusion (A))



LED strip (B)



Cover (C)



End cap (D)


### Tools needed for mounting:

- mounting tape

**WARNING!** All LED strips should be connected to a 12 V or 24 V power supply.

**IMPORTANT:** The mounting instructions present the basic form of assembly.  
More methods and related accessories can be found at [www.KlusDesign.eu](http://www.KlusDesign.eu)

1. Install the LED strip (B) in the extrusion (A), insert the cover (C) and the end caps (D).



2. Feed the power cable. Attach the mounting tape to the upper part of the extrusion (A). Attach the entire fixture to the chosen location.

