


Parts needed to mount the TAMI extrusion



Extrusion (A)



End caps (B)



Cover (C)



LED strip (D)


Tools needed for mounting:

- mounting glue


NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure.
More mounting procedures and related accessories can be found at klusdesign.com

1. Mount the LED strip (D), insert the cover (C),and insert the end cap (B).



2. Feed the power cable. Spread the glue on the surface.



3. Connect power to the LED strip and mount the extrusion (A) in the mounting channel.

