


Parts needed to mount the SEKODU extrusion



Extrusion (A)



End caps (B)



Cover (C)



LED strip (D)




Spring (E)


NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure. More mounting procedures and related accessories can be found at klusdesign.com

1. Feed the power cable. Mount the LED strip (D), insert the cover (C), and then insert the end cap (B).



2. Insert the spring (E) into the grooves in the extrusion (A).



3. Connect power. Pull the springs inward and insert the extrusion (A) into the mounting groove.

