

Parts needed to mount the PDS-MDF extrusion



Extrusion (A))



LED strip (B)



Cover (C)



End cap (D)


Tools needed for mounting:

- mounting tape

WARNING! All LED strips should be connected to a 12 V or 24 V power supply.

IMPORTANT: The mounting instructions present the basic form of assembly. More methods and related accessories can be found at www.KlusDesign.com

- 1.** Install the LED strip (B) in the extrusion (A), insert the cover (C) and the end caps (D).



- 2.** Feed the power cable. Attach the mounting tape to the upper part of the extrusion (A). Attach the entire fixture to the chosen location.

