




Parts needed to mount the KRAV-05IN profile



Extrusion (A)



End cap (B)




LED strip (C)


NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure.
More mounting procedures and related accessories can be found at klusdesign.com


- 1.** Attach the LED strip (C) to the lower part of the extrusion (A) with glue and insert the power cable.




- 2.** Degrease the glass and attach the upper part of the extrusion (A).



- 3.** Attach the lower part of the extrusion (A) with glue.



- 4.** Insert the end caps (B).



- 5.** Connect power.

