


**Parts needed to mount the LARKO-50 extrusion**

Extrusion (A)



End caps (B)



Cover (C)



LED strip (D)



Springs (E)


Tools needed for mounting:

- springs for grooves
- screwdriver


WARNING! All LED strips should be connected to a 12 V or 24 V power supply.

IMPORTANT: The mounting instructions present the basic form of assembly.
More methods and related accessories can be found at www.KlusDesign.com


- 1.** Drill a hole in the extrusion for the power cable.



- 2.** Mount the LED strip (D) in the extrusion, lead out the power cable, insert the cover (C).



- 3.** Slide the springs (E) into the extrusion (A) channels and screw the end cap (B).



- 4.** Connect power and mount the extrusion (A) by bending the springs.

