





1. Attach the mounting bracket to the surface with screws.



2. Insert the extrusion in the mounting bracket.



NOTE! A list of products corresponding with the selected accessories is available at www.KlusDesign.com