


Tools needed when mounting:


- drill

ATTENTION! List of products compatible with selected accessories available on the website.


1. Drill a hole in the concrete wall 10mm in diameter.



2. Insert the M5 mounting set into the drilled hole.



3. Insert the selected fixture/ extrusion into the mounting bracket.



4. ATTENTION! POSITION OF THE FIXTURE CAN BE REGULATED on the arm in a range of 300 degrees.300°.

